

**VA-1 Clamp-on Meter
Model 50106-G-01**

- Fast, well damped meter movement
- Enables the operator to get quick, accurate, reliable, safe measurements of both voltage and alternating current without interrupting the circuit
- Carrying strap slot
- Measures AC current 10-1000 amperes
- Measures voltage of 175/350/700 @ 50 to 70Hz
- Voltage leads plug into the side of the meter case
- Can be hung on conductor, leaving operator's hands free
- 500 Amp maximum continuous duty
- The dial can be lighted on request
- Accuracy is $\pm 3\%$ FS
- Positive, convenient selector switch
- Rugged, unbreakable case
- Safety style trigger designed for glove or barehanded use
- Maximum operating temperature—5°F to 150°F (-20°C to +65°C)