
**OPERATING INSTRUCTIONS for
Model 30120-G-01 - GRAY BOX TESTER**

CAUTION:

**THE PROOF TESTER GENERATES HIGH VOLTAGE. CARE SHOULD BE
TAKEN TO PREVENT CONTACT WITH THE VOLTAGE TEST POINT!**

- I. SET UP
- A. Ensure battery is properly connected to the proof tester: Black wire to (-) and red wire to (+)
 - B. To operate tester, move the “on-off” switch lever (located on the top right side of the tester to the “on” position
 - C. Follow proper proof testing procedures for the particular meter under test

NOTE:

**POSITIVE DEFLECTION OF THE METER DURING PROOF TESTER
OPERATION DOES NOT PROVE ACCURACY OF CALIBRATION. THE
VOLTMETER SHOULD BE SCHEDULED FOR ANNUAL CALIBRATION
CHECKS AND INSPECTIONS FOR SAFETY AND RELIABILITY.**

NOTE: Since STB Electrical Test Equipment, Inc. has the policy of continuous product improvement; we reserve the right to change design, specifications, and/or prices without notice.

Rev. 04/2007